

VEHICLE INSPECTION REPORT

SH71GHJ

Fiat Doblo Work Up 1.6 Multijet 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 31/12/2021

Year 2021

Mileage 78,366 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V39620

Body Style Pick-up

MOT Due 30/12/2025

CAP Clean £6,400.00

CAP Average £5,825.00

CAP Below £4,900.00

Gearbox MANUAL

Gears 5

WARNING LIGHTS ON DASH, HANDBRAKE POOR AD-BLUE

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Park assist camera
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Dented
Over 30mm (Steel)



5: Sill ns
Dented
Over 30% Of Panel



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Sill os
Dented
With Paint Damage



11: Wing osf
Dented
With Paint Damage



12: Screen Front
Chipped
Over 10mm



13: Door Pad osf
Broken
Replace



14: Fascia Panel
Missing
Replace



15: Seat Base Cover osf
Torn
Over 3mm



16: Seat Back Cover osf
Torn
Over 3mm



17: Seat Base Cover nsf
Soiled
Heavy



18: Door Pad nsf
Soiled
Heavy



19: Carpets Front
Holed
Over 3mm



20: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		