

VEHICLE INSPECTION REPORT

YJ13HUV

Vdl Futura FHD2-129

Serious Damage Inspection

Serious Damage? Yes

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	17/04/2013	Colour	WHITE	Cab Type	DAY CAB
Year	2013	VIN	XNL501E100D002274	Gearbox	AUTOMATIC
Mileage	743,959 Km Not Warranted	Body Style	Coach	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/10/2025	Rear Suspension	Air

WARNING LIGHT ON DASH, TWO SMASHED WINDOW PANELS, NO ACCESS TO TOILET, W/CHAIR LIFT INOPERABLE 49 SEATS + 1 WHEELCHAIR, DRIVER & CREW SEAT, PANEL SYSTEM, ENTERTAINMENT SYSTEM, UNDERBODY STORAGE, OVERHEAD STOWAGE, RECLINING SEATS, REAR EXIT

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Cloth seat trim
- Digital radio
- Radio/CD

Photos










Condition Check



Damage Photos



1: Screen Front
Cracked
Replace




2: Door Mirror Assy nsf
Broken
Replace



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
Over 30mm



9: B Post ns
Cracked
Replace



10: Qtr Panel osr
Dented
With Paint Damage



11: Door osr
Dented
With Paint Damage



12: Qtr Panel osr
Dented
Over 30mm



13: Door Window osr
Missing
Replace



14: Door Window osr
Missing
Replace



15: Door Mirror Assy osf
Broken
Replace



16: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		