

VEHICLE INSPECTION REPORT

LM66ZZN

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 05/12/2016

Year 2016

Mileage 154,276 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9061352N689508

Body Style Dropside

MOT Due 04/12/2025

CAP Clean £4,275.00

CAP Average £3,550.00

CAP Below £2,650.00

Gearbox MANUAL

*OUTSTANDING RECALL **WARNING LIGHT ON DASH* AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Broken
Replace



4: Bumper Front
Cracked
Over 25mm



5: Wing nsf
Dented
With Paint Damage



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door osf
Dented
Over 30mm



9: Door osf
Dented
Over 30mm



10: Door osf
Dented
Over 30mm



11: Door Mirror Assy osf
Broken
Replace



12: Wing osf
Scratched
Over 25mm Thru Paint



13: Door Pad osf
Soiled
Heavy



14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover osf
Soiled
Heavy



16: Seat Base Cover nsf
Soiled
Heavy



17: Door Pad nsf
Soiled
Heavy



18: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition
Seat Condition

Poor
Poor

Upholstery Condition
Odour

Poor
Yes

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		