

VEHICLE INSPECTION REPORT

WR20DWU

Fiat Ducato 35 2.3 MULTIJET 140PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	44846
		Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Bedford	GVW	3500kg	CAP Clean	£6,525.00
Reg. date	29/06/2020	Colour	WHITE	CAP Average	£5,725.00
Year	2020	VIN	ZFA25000002N79974	CAP Below	£4,600.00
Mileage	82,878 Miles Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	01/07/2027	Gears	6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Front parking sensor
- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Roof
Dented
With Paint Damage



3: Bonnet
Chipped
Multiple Chips



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Carpets Front
Holed
Over 3mm



8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK