

VEHICLE INSPECTION REPORT

BF18YRU

Fiat Ducato 35 2.3 MULTIJET 150PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 23/03/2018

Year 2018

Mileage 117,162 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002E35655

Body Style Dropside

MOT Due Expired

CAP Clean £4,125.00

CAP Average £3,550.00

CAP Below £2,800.00

Gearbox MANUAL

Gears 6

Tail Lift Column

TOW BAR, E/ MIRRORS, WEIGH SYSTEM

Tyres

NSF

NSR

OSF


OSR

Spare


Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Navigation system
- Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking

Photos



Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Bumper Front
Dented
Over 30mm



4: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door osf
Chipped
Multiple Chips



6: Wing osf
Scratched
Over 25mm Thru Paint



7: Door Pad osf
Soiled
Heavy



8: Carpets Front
Holed
Over 3mm



9: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		