

No

VEHICLE INSPECTION REPORT

CU68KGX

FORD TRANSIT 350 2.0 TDCI 130PS

Vehicle VAT

Buyer To Apply
WF0JXXTTGJJJ14472 Gears 6 Curtainside L4
WF0JXXTTGJJJ14472 Gears 6 Curtainside L4
Curtainside L4
26/11/2025
20/11/2020

Plus VAT

Features

Inspection

Serious Damage?

- Bluetooth connection
- · Drivers airbag
- Auxiliary input socketPassenger airbag
- Digital radioCentral locking
- Front electric windows
- · Cloth seat trim

Photos

OSF **OSR** Spare

















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Door Pad osf Soiled Heavy



3: Seat Base Cover osf Soiled Heavy



4: Seat Base Cover nsf Soiled Heavy



5: Fascia Panel Broken Replace

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	Poor No	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			