

VEHICLE INSPECTION REPORT

HV09GUC

MERCEDES-BENZ ACTROS

Inspection Vehicle

VAT	Plus VAT	
V5	To Follow	

Details

Reg. date	10/08/2009	Colour	YELLOW	Gearbox	MANUAL
Year	2009	VIN	WDB9302052L351400	Axle Combi	6x2
Mileage	340,621 Km Not Warranted	Body Style	Vacuum Tanker	Rear Suspension	Air
		Cab Type	SLEEPER CAB		
Fuel Type	Diesel			•	

GULLY ATTACHMENT, REAR HOSE ASSEMBLY, AD-BLUE, SLIDING 5TH WHEEL

Tyres

NSF

NSR

OSF

OSR

Spare

Features

• Digital radio

Photos















